

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page 1 of 4
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 09/02/2008
Test Type: Smoke	Ground Condition: Dry: X Damp: _ Wet: _	Supervisor: E.R. Crew: 04
Manhole ID: S17O__009MH	Test ID: 1029-588	Notifications Made: __X__ Residents, Fire, 311
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)		

[illegible]

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 588	Date: 09/02/2008	Basin: LL - 44	Manhole ID: S17O__009MH
Defect No: OB01	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: 2418 CHRISTIAN ST.			
Source Type: 03 Cleanout		Sector: 02 Private	
Location: 08 Yard - Back		Severity: 03 Moderate	Drainage Area: 2
Comments: SMOKE IS COMING FROM THE BELOW GRADE CLEANOUT WITHOUT CAP.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01
Filename: 1029-588_OB01-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 588	Date: 09/02/2008	Basin: LL - 44	Manhole ID: S17O__009MH
Defect No: OB02	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: S17O__027MH			
Source Type: 18 Other		Sector: 01 Public	
Location: 02 Asphalt		Severity: 03 Moderate	
Comments: MANHOLE S17O__027MH HAS A STORM DRAIN LID.		Drainage Area: 6	

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01
Filename: 1029-588_OB02-01.jpg